DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-003438

Address: 333 Burma Road **Date Inspected:** 01-Aug-2008

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 1400 **OSM Departure Time:** 2230 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Huang Wen Pang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG

Summary of Items Observed:

Caltrans Quality Assurance (QA) Inspector, Larry Viars was present to observe fabrication and perform Ultrasonic Testing (UT) of Orthotropic Box Girder (OBG) components, for the San Francisco Oakland Bay Self Anchored Suspension Bridge, at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

Sub Assembly Shop Bay # 7

The Caltrans QA Inspector performed UT verification of ZPMC Quality Control (QC) inspected and accepted Floor beam Complete Joint penetration welds, FB014-008-043 & 044, FB014-011-043, FB014-008-043 & 044, FB014-007-043 & 044, FB013-011-043 & 044, FB013-006-044, FB028-002-126 (R2) and FB028-002-127 (R2). The welds tested appeared to be in general conformance with AWS D1.5 table 6.3 and contract documents. See UT report TL-6027 generated on this date for further information.

OBG Assembly Shop Bay # 2

The Caltrans QA Inspector performed 10% verification Magnetic particle Testing (MT) on the following fillet welds joining T-stiffeners to side and bottom panels on OBG section 4BW: SP-038-001 and SP062-001. All of the welds that were examined appeared to comply with AWS D1.5 2002 and the contract documents. See MT report TL-6028 generated on this date for further information.

Summary of Conversations:

Only general conversations between Caltrans QA and QC occurred this date.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Ady Velasco, 138 1694 2685, who represents the Office of Structural Materials for your project.

Inspected By:	Viars,Larry	Quality Assurance Inspector
Reviewed By:	Lanz,Joe	QA Reviewer